



PRODUCTS IN USE

Column Load Cells (LCA Series) paired with USB Solutions.

APPLICATION SUMMARY

Press (Hydraulic or Pneumatic) verification testing is a necessary requirement within the automation process. By implementing load cells with USB output, the operator can verify the uniform loading of a large platform. Each load cell serves as a monitoring point within the system.

All FUTEK application illustrations are strictly conceptual. Please contact us with questions.

